

MUNICIPAL CORPORATION OF DELHI
Public Health Department
Shahdara (South) Zone
419, Udyog Sadan,
Patparganj Industrial Area Delhi-110092

No. DHO/Shah.(S)/2025/D- 1149

Dated:-30/6/25


School Health Certificate

1. Name of School	: Salwan Public School
2. Location of the School	: Mayur Vihar Ph-III Kondli Gharoli, Complex New Delhi-110096
3. School timing	: 8:40AM to 02:30PM
4. No. of Students	: 1631
5. No. of Doors in each room	: Provided
6. No. of Fans in each room	: Provided
7. Building Structure	: Pucca
8. Electricity	: BSES
9. Water Supply	: DJB supply
10. No. of Urinals and WCS	: Provided
11. No. of Teaching Staff	: 63
12. No. of Tab	: Provided
13. No. of Rooms	: 74
14. No. of Bathrooms & lavatories for boys	: 64
15. No. of Bathrooms & lavatories for girls	: 42

At the time of inspection, school is found running under sanitary and hygiene conditions. This certificate has no bearing on unauthorized construction of the premises if any and on any dispute regarding title of land.


This certificate/NOC is valid for (01) one year only.

The Principal
Salwan Public School
Mayur Vihar Ph-III,
Kondli Gharoli, Complex,
New Delhi-110096


Deputy Health Officer
Shahdara (South) Zone
Deputy Health Officer
Shahdara South Zone
Municipal Corporation of Delhi




Principal
Salwan Public School
Kondli Gharoli Complex
Mayur Vihar Phase-III,
Delhi-110096


Director
Salwan Public School
Kondli Gharoli Complex
Mayur Vihar Phase-III,
Delhi-110096

 Delhi Jal Board No.DJB/QCLTYR/PD/251205	DELHI JAL BOARD (GOVT. OF N.C.T. DELHI) QUALITY CONTROL LABORATORY, TRANS YAMUNA REGION TAHIRPUR DELHI-110093	 एक कदम स्वच्छता की ओर
	 Licence No- CRO/QMWL-8004274-1 as per IS/ISO 9001:2015	

NO: DJB/ACWA(TYR)/2025.....195

DATE:- 20-12-2025

Analysis report of DJB water supply samples collected from (1) Inlet, (2) Outlet of **M/S SALWAN PUBLIC SCHOOL, KONDLI GHAROLI COMPLEX, MAYUR VIHAR PHASE-III, DELHI-110096** for drinking purpose.

Ref. No. SPS/MV/2025-2026/5841,

dated: - 05.11.2025

Challan No: - 224,

dated: - 16.12.2025

Date of collection: 18.12.2025

Date of Collection: 15/12/2023						
S. No.	PARTICULARS	BIS:10500-2012 LIMITS		UNITS	RESULT	
		Desirable	Permissible		(1)	(2)
A.	Physical Examination					
1.	Colour	...	...	-	CLEAR	CLEAR
2.	Odour	...	...	-	CHLOR.	CHLOR.
3.	Turbidity	1.0	5.0	NTU	3.46	3.71
4.	pH Value	6.5-8.5	--	-	7.5	7.5
5.	Electrical Conductivity	--	--	µs/cm	285	310
6.	Total Dissolved Solids	500	2000	mg/l	185	201
B.	Chemical Examination					
7.	P ^h Alkalinity	...	...	mg/l	NIL	NIL
8.	Total Alkalinity	200	600	mg/l	96	96
9.	Total Hardness	200	600	mg/l	104	116
10.	Calcium as (Ca)	75	200	mg/l	31.2	38.4
11.	Magnesium as (Mg)	30	100	mg/l	6.24	4.80
12.	Ammonical Nitrogen	0.5	NR	mg/l	N.D	N.D
13.	Nitrite			mg/l	N.D	N.D
14.	Nitrate	45	NR	mg/l	7.34	5.99
15.	Sulphate	200	400	mg/l	39.95	45.56
16.	Chloride	250	1000	mg/l	12	16
17.	Fluoride	1.0	1.5	mg/l	0.06	0.06
18.	Dissolved Iron	1.0	NR	mg/l	0.14	0.18
19.	Cyanide	0.05	NR	mg/l	N.D	N.D
20.	Residual Chlorine	0.2	1.0	mg/l	1.00	0.30
C.	Bacteriological Examination					
21.	Coliform count	Absent	NR	MPN/100ml	0	0

REMARKS:- On the basis of above tested parameters, both water samples conform to the prescribed limits and can be considered fit for drinking purpose.

(B. Sheikhs Lal)

ACWA(TYR)

Asstt. Chief Water Analyst

D.J.B. Govt. of N.C.T. of Delhi

Quality Control Zonal Laboratory (Tyr)

Tahirpur Dilshad Garden, Delhi-93

(A.G. Susmitha)

BACTERIOLOGIST

(Gulesh Jainar)

CHEMIST

(Gyaneshwar Prasad)

A/CHEMIST

Director

Principal
Salwan Public School
Kondli Gharouli Complex
Mayur Vihar Phase-III,
Delhi-110096

Salwan Public School
Kondli Gharouli Complex
Mayur Vihar Phase-III,
Delhi-110096